

State of Utah

GARY R. HERBERT Governor

GREG BELL
Lieutenant Governor

June 15, 2010

C/007/042 Incoming

Environmental Quality

Amanda Smith

Department of

DIVISION OF WATER QUALITY Walter L. Baker, P.E. Director

Executive Director

Mr. Rusty Netz, Environmental Coordinator Sunnyside Cogeneration Associates P.O. Box 10 East Carbon, Utah 84520

Subject:

Reconnaissance Inspection Report for the Sunnyside Cogeneration Associates

Star Point Refuse Pile - UPDES Permit No. UTG040025

Dear Mr. Netz:

On June 8, 2010 I conducted a Reconnaissance Inspection, while already in the area, with regards to your facility and the UPDES Permit referenced above. There were no deficiencies noted and no response is required at this time.

Enclosed are copies of the inspection reports for your records. If you have any questions, please contact me at my new phone number (801) 536-4395 or by e-mail at jstudenka@utah.gov. Also, please note below our new address for future mailings. Thank you.

Sincerely,

Jeff Studenka, Environmental Scientist

tudenka

**UPDES IES Section** 

**Enclosures** 

cc (w/encl):

Amy Clark, EPA Region VIII

Claron Bjork, SE District Health Department

Dave Ariotti, SE District Engineer

Daron Haddock, Division of Oil Gas & Mines

F:\wp\GP-Coal Mines\SunnysideCogen\RI June 2010 cov.ltr.doc

RECEIVED

JUN 2 1 2010

DIV. OF OIL, GAS & MINING



United States Environmental Protection Agency Washington, D.C. 20460

### Water Compliance Inspection Report

Section A: Nation	al Data System Coding (i.e., 1	ICIS)			
Transaction Code  NPDES  U T G 0 4 0 0 2 5  1 3	yr/mo/day  12 0 0 6 0 8	Inspection Ty	pe Inspector Fac. Type  S 19 20		
21			66		
Inspection Work Days    1   67   69   Facility Self-Monitoring Evaluation Rating   4   70   70	BI QA N N 72	73 74	Reserved		
Sec					
Name and Location of Facility Inspected (For industrial users discharging and NPDES permit number)	to POTW, also include POTW name	Entry Time/ Date 1:45 pm /6-8-2010	Permit Effective Date 5-1-2008		
Sunnyside Cogeneration Associates Star Point Coal Mine Refuse Pile Facility Wattis, Utah off Hwy. 122 in Carbon County, UT		Exit Time/ Date 2:00 pm / 6-8-2010	Permit Expiration Date 4-30-2013		
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)		Other Facility Data (e.	s., SIC NAICS, and other		
N/A		descriptive information			
		Former Coal Mining SIC Code 1222 NAICS 212112	Operations		
Name, Address of Responsible Official/Title/Phone and Fax Number Rusty Netz, Environmental Coordinator (435) 888-447, Sunnyside Cogeneration Associates #1 Power Plant Road Sunnyside, UT 84539	Contacted	SEE ATTACHED			
Section C: Areas Evaluated Dui	ring Inspection (Check only th	ose areas evaluated	0		
Permit  Records/Reports  Facility Site Review  Effluent/Receiving Waters  Flow Measurement  Self Monitoring Progr  Compliance Schedule  Laboratory  Departions & Mainten  Sludge Handling/Disp	ntion or Overflow Overflow	MS4			
Section D: Su (Attach additional sheets of narrative and ch	as necessary)				
SEV Codes SEV Description	The state of the s				
Name(s) and Signature(s) of Inspector(s)  JEFF STUDENKA, ENVIRONMENTAL SCIENTIST  CH Studies	Agency/Office/Phone and Fax Number(s)  DWQ (801) 536-4395		Date: 6-15-2010		
N/A					
Name and Signature of Management Q A Reviewer  MIKE HERKIMER, MANAGER  UPDES IES SECTION  EPA Form 3560-3 (Rev 1-06) Previous editions are obsolete	Agency/Office/Phone and Fax Number(s) DWQ (801) 536-4390		Date: 6/15/10.		

#### INSPECTION PROTOCOL

**UPDES Permit #:** 

UTG040025 – Sunnyside Cogeneration Associates (SCA)Star Point Coal Pile

Inspection Type:

Reconnaissance Inspection (RI)

Inspection Date:

June 8, 2010

Weather Conditions: Sunny and warm, ~75°F

Jeff Studenka of the Division of Water Quality (DWQ) visited the Star Point Coal Refuse Pile, while already in the area, to perform a RI. There were no deficiencies noted during the last inspection for follow up (7-29-2009 RI).

#### **FACILITY DESCRIPTION**

Location:

Former Star Point Mine Site in Wattis, Utah off State HWY. 122 in Carbon County.

Coordinates: Outfall 005 – 39° 31' 38.91" latitude, -111° 00' 41.23" longitude (Pond-5)

Outfall 006 – 39° 31' 47.64" latitude, -111° 00' 14.11" longitude (Pond 6)

Outfall 009 – 39° 31' 37.36" latitude, -111° 00' 33.30" longitude (Pond 9)

Average Flow: 0.0 MGD (only 1 minor discharge in past six years from heavy rainfall Nov. 2004)

Receiving waters: Serviceberry Creek (dry)

<u>Processes</u>: Refuse coal from the former Star Point mine is managed by SCA and is regularly trucked to their cogeneration power plant in Sunnyside, UT. Three sedimentation ponds remain on site to capture surface water from runoff events. Over the past six years, there has been only one discharge event. Outfalls 005 & 006 discharged one day in November 2004 from a major storm event.

#### **INSPECTION SUMMARY**

The outfall locations were observed as well as the dry receiving streambed of Serviceberry Creek. At the time of the inspection, portions of the coal pile were being relocated to other areas on site as natural gas pads have been proposed nearby. The three sedimentation ponds were observed to be in good condition and mostly dry with no evidence of discharges. A few photos were collected for the file and are included herein.

#### **DEFICIENCIES**

No deficiencies were noted during the inspection.


#### REQUIREMENTS

None.

Sunnyside Cogen's Star Point Refuse Pile

Photo Log (UTGO40025)						
Photo Number	File Name Description		Date/ Time		Photographer	
		Entrance Gate Near Wattis, UT	6-8-1	0	JS	
(2)	_	Coal Refuse Pile being relocated	6-8-	10	ZL	
3	-	Sedimentation food near coal file	6-8	140	JS	
4	_	Small sed pond along road	6-8	i d	JS	
-	END-					
r.						
				100		

# Sunnyside Coopen's Star Point Refuse Pile (UTG040025)



## Sunnyside Cogen's Star Point Refuse Pile (UT6,040025)

